



TRANSPOWER



Customer Advice Notice

Revision

To: SO Notice NZ Participants

From: The System Operator

Sent: 02-oct-2026 16:57

Telephone: 0800 488 500

Ref: 800000294

Email: NMData@transpower.co.nz

Revision of: CAN, 800000290, 6-aug-2026 16:33, Huntly BESS (HLY11) to be classified as a Secondary Risk while commissioning (Update)

Huntly BESS (HLY11) to be classified as a Secondary Risk while commissioning (Update)

Transpower as System Operator advises that from **17:30, 2 October 2026, Huntly BESS (HLY11)** will no longer be classified as Secondary Extended Contingent Event (ECE) Risk.

~~During this time:-~~

- ~~• Secondary CE Risk of up to 20 MW will be added to the reserve requirement. An update will be sent when the Secondary CE Risk is cleared.~~
- ~~• Secondary ECE Risk of up to 100 MW will be added to the reserve requirement. An update will be sent when the Secondary ECE Risk is changed or cleared.~~

~~Other updates will be sent if there is any change to these risk classifications or the commissioning time frames.~~