



# Hazardous Substances - used by Transpower staff on Transpower business

December 2023





Shading at top indicates CRITICAL control(s)

Shading at base indicates control hierarchy

ELIMINATE / ENGINEERING / PROCESS / PEOPLE


\*\*Asbestos Containing Material (ACM)

\*\*\* Asbestos Management Plan (AMP)

\*Asbestos is not treated as a hazardous substance under the HSE regulations, we use the term to manage it, but it has a separate classification and requirements

Relevant policies and procedures include Approved Codes of Practice (ACOPs), Codes of Practice (COPs), Drug & Alcohol policy and procedures Remote and Lone Working Procedures, Fatigue management procedures Asbestos Management Plan, Service Specifications, Procurement procedures. Environmental Panel & Best Practice Guide for managing contaminated soil at Transpower substations

Sulphur Hexafluoride (SF6) – Draft




Shading at top indicates CRITICAL control(s)

Shading at base indicates control hierarchy

ELIMINATE / ENGINEERING / PROCESS / PEOPLE

**Adherence to Service Specification \*SF6 Gas Maintenance & Management TP.SS 02.29.** Other relevant policies and procedures include Drug & Alcohol policy and procedures Remote and Lone Working Procedures, Fatigue management procedures Safety Data Sheets (SDS), standards & Service Specifications, Procurement procedures Environmental Panel & Best Practice Guide for managing contaminated soil at Transpower substations



Shading at top indicates CRITICAL control(s)

Shading at base indicates control hierarchy  
**ELIMINATE / ENGINEERING / PROCESS / PEOPLE**

Relevant Standards, policies, procedures & guidelines include \*Original Equip Manufacturer (OEM) \*\*Compliance with Electrical equipment in hazardous areas AS/NZS 60079.14:2009 Standard and Hydrogen management \*\*\*SOPs. Drug & Alcohol policy and procedures Remote and Lone Working Procedures, Fatigue management procedures Service Specifications, Procurement procedures