



Grid Emergency Notice

Revision

To: GEN SI Participants
Sent: 23-oct-2025 07:55
Ref: 6757406725

From: The System Operator
Telephone: 0800 488 500
Email: NMDData@transpower.co.nz

Revision of: **GEN, 6757038838, 23-oct-2025 07:43, Severe Weather Upper South Island**

Cause: Severe Weather Upper South Island Upper South Island
Region or GXP affected: Top of South Island
Starting: 23-oct-2025 07:30
Ending: 23-oct-2025 18:00

Due to Severe Weather in the Upper South Island to manage system security. Greymouth- Kumara-1 circuit has been removed from service.

Consequences on the power system:

Risk of exceeding n-1 voltage stability security margin.
 System operator needs to reconfigure the grid the effect restoration.

The system operator advises:

Grid reconfiguration has occurred
 Managed restoration of load will occur

At:

Upper South Island
 Upper South Island

Demand Allocations:	Total	Notes
---------------------	-------	-------

Consequences if insufficient responses by participants:

For more information contact the Security Coordinator on 0800 488 500

This notice is issued in accordance with Technical Code B - Emergencies, Schedule 8.3, Part 8

A revision of this notice will be issued if there is any change to the situation above.