



TRANSPOWER



Grid Emergency Notice

Revision

To: GEN SI Participants
Sent: 23-oct-2025 12:54
Ref: 6757902479

From: The System Operator
Telephone: 0800 488 500
Email: NMDData@transpower.co.nz

Revision of: **GEN, 6757406725, 23-oct-2025 07:55, Severe Weather Upper South Island**

Cause:	Severe Weather Upper South Island Upper South Island	
Region or GXP affected:	Top of South Island	
Starting:	23-oct-2025 07:30	23-oct-2025 07:30
Ending:	23-oct-2025 18:00	23-oct-2025 13:00

Due to Severe Weather in the Upper South Island to manage system security.
Greymouth- Kumara-1 circuit has been removed from service.

Consequences on the power system:

Risk of exceeding n-1 voltage stability security margin.
System operator needs to reconfigure the grid the effect restoration.

The system operator advises:

Grid reconfiguration has occurred
Managed restoration of load will occur

At:

Upper South Island
Upper South Island

Demand Allocations:

Total

Notes

Consequences if insufficient responses by participants:

For more information contact the Security Coordinator on 0800 488 500

This notice is issued in accordance with Technical Code B - Emergencies, Schedule 8.3, Part 8

A revision of this notice will be issued if there is any change to the situation above.